

**PRIORITY**  
OUT56257

26 JUL 1965

TOP SECRET 232100Z

1965 JUL 23 21 12Z

PRIORITY   5033

IDEALIST

ATTENTION:  

SUBJECT: EVALUATION OF MISSION C065C

COPIES DESTROYED		
Cy No.	Office	Act.
1	CS	25X1
2	ADJ-GEN	25X1
	SEC-ER	
	IN-OS	
	OSD	
	IN-0	
	PD	
	PSD	
3,4	FSD-ICB	
	TID	
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

1. CAMERA B 118 WAS USED IN MISSION C065C FLOWN ON 24 FEBRUARY 1965. PROCESSING WAS ACCOMPLISHED IN THE FIELD.


## 2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND RESOLUTION IS GOOD.

B. 9R SIDE: ROLLER CHATTER AND EDGE STATIC FOGGING ARE PRESENT INTERMITTENTLY ALONG BOTH EDGES. MINOR EDGE FOG OCCURS ALONG BOTH EDGES THROUGHOUT THE MISSION. ABRASIONS ARE NOTED ON FRAMES 1642, 1704 AND 1706. FILM TEARS ACROSS THE MINOR AXIS OCCUR ON FRAMES 1706, 1715 AND BETWEEN 0018/0019. FOGGING, ALONG WITH PROCESSING STAINS AND STREAKS, OCCUR ON NUMEROUS FRAMES BETWEEN 1649 AND 1722.

C. 9L SIDE: MINOR EDGE FOG AND STATIC OCCUR INTERMITTENTLY THROUGHOUT THE MISSION. ROLLER CHATTER IS PRESENT INTERMITTENTLY ALONG THE INBOARD EDGE. FILM TEARS ACROSS THE MINOR AXIS OCCUR ON FRAMES 0503 AND 0910. A MANUFACTURING SPLICE IS PRESENT ON FRAME 0669.

D. BOTH SIDES: THE FIRST CLOCK NUMBERED FRAME IS 0246. CLOCK NUMBERED FRAMES 0357 TO 0430 HAVE BEEN EDITED FROM THE



25X1

-2-

MISSION. HEAT SPLICES ARE PRESENT BETWEEN TITLED FRAMES 26/27, 110/111, 218/219, 351/352, 484/485, 617/618, 750/751, 883/884, 1016/1017, 1049/1050, 1282/1283, 1415/1416, 1548/1549, 1681/1682, 1814/1815, 1947/1948, 2080/2081. THE LAST TITLED FRAME IS 2090.

E. THE STAINS AND PROCESSING STREAKS ON THE 9R SIDE WERE POSSIBLY CAUSED BY A PROCESSING BREAKDOWN. THERE WERE NO MAJOR CAMERA MALFUNCTIONS DURING THE MISSION.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADED OR OBSCURED 3 PER CENT OF THE MISSION PHOTOGRAPHY.

T O P S E C R E T

-END OF MESSAGE-